

Date:

Region:

CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



Original Work Request:

There is a water supply line valve severely corroded that services the new RTU just inside the boiler room. Needs repaired/replaced.

Description of Repairs Needed:

Investigate and troubleshoot to diagnose issues with the Burnham boiler. 3-way valve is corroded and needs to be replaced and the boiler needs servicing.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	7	\$ 138.00	\$ 966.00
Trip Charge	1	\$ 218.75	\$ 218.75

Material List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,184.75	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,184.75	\$142.17	\$71.09	\$1,398.01