

Additional Funding Request

WITH INVOICE

Submitted: **7/15/2022**

VA002-No Hot Water	CSS #1653 WO#18471											
Description of Repairs	Troubleshoot hot water issues. Found the heater was tied in to the same breaker as the boilers so the breaker was turned back on. Cleared condensate drain in wall unit upstairs. Cleared floor drain in mechanical room that was backed up. Work complete.											
Original SC Investigative Diagnosis	\$NA											
Diagnosis: Initial Work Order	No Hot Water in the Building											
Explanation of Additional Costs for Repairs	N/A											
Additional Material Cost to Perform Repairs	Materials: \$ 64.63 <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: center; padding: 2px;">QUANTITY</th> <th style="text-align: center; padding: 2px;">UNIT PRICE</th> <th style="text-align: center; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="padding: 2px;">Parts detailed on invoice</td><td style="text-align: center; padding: 2px;">1</td><td style="text-align: center; padding: 2px;">\$64.63</td><td style="text-align: center; padding: 2px;">\$64.63</td></tr> </tbody> </table>				ITEM	QUANTITY	UNIT PRICE	TOTAL	Parts detailed on invoice	1	\$64.63	\$64.63
ITEM	QUANTITY	UNIT PRICE	TOTAL									
Parts detailed on invoice	1	\$64.63	\$64.63									
Additional Labor Cost to Perform Repairs	Labor: \$500.00 5 hours each/Plumbing Rate \$100.00 per hour = \$500.00											
Total Cost of Repair	\$564.63											