

**Region: 5**

**Location: VA002**

**CSS # 33682**

**Maximo Work Order No.: 15962**

**Asset #: NA**

**Date Issued: 12/27/2021**

**Original Description: Additional Efforts:Replaced DIS Board ,Re-terminate, Reprogram, and Test the Reader at the Gate, the Aiphone System, and the Gate Operator.**

**Repairs Needed:**

LoCurrent Systems is pleased to provide a Follow Up Quotation, per Estimate #1880 (WO 15656), to Pull new cable, Re-Terminate, Reprogram, and Test the Reader at the Gate, the Ai phone System, and Gate Operator at the Alexandria, VA Lieber Center. While on site, LoCurrent Systems found cabling was severely damaged, and in need of replacement in order to ensure systems are fully operational. DIS Board installed with WO 15656

**RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):**

| Quantity | Line Item Number | Description                | Labor Hours | Labor Rate/Hr | Materials  | Equipment | Total      |
|----------|------------------|----------------------------|-------------|---------------|------------|-----------|------------|
| --       | NA               | Parts (See attached Quote) | --          | --            | \$1,172.00 | --        | \$1,172.00 |
| --       | NA               | Labor (2) 16 hrs each      | 32          | \$85.00       | --         | --        | \$2,720.00 |

**Estimate Summary:**

| Labor Hours | Labor Cost | Material Cost | Equipment | Total Cost | CE Factor | Total Estimate    |
|-------------|------------|---------------|-----------|------------|-----------|-------------------|
| 32          | \$2,720.00 | \$1,172.00    | NA        | \$3,892.00 | 100%      | <b>\$3,892.00</b> |