

## Additional Funding Request

### WITH INVOICE

Submitted: 3/01/2022

<b>VA002-Female toilets</b>	<b>CSS #34395 WO#16423</b>											
Description of Repairs	Replaced Sloan valve on left most stall and tested that it now flushes properly. Replaced the broken/leaking faucet in women's room with a new faucet. Work complete.											
Original SC Investigative Diagnosis	<b>\$NA</b>											
Diagnosis: Initial Work Order	2 upstairs Female toilets are not flushing properly											
Explanation of Additional Costs for Repairs	N/A											
Additional Material Cost to Perform Repairs	<b>Materials: \$486.71</b> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;"><b>Parts see detail in attached quote</b></td><td style="text-align: left; padding: 2px;"><b>1</b></td><td style="text-align: left; padding: 2px;"><b>\$486.71</b></td><td style="text-align: left; padding: 2px;"><b>\$486.71</b></td></tr> </tbody> </table>				ITEM	QUANTITY	UNIT PRICE	TOTAL	<b>Parts see detail in attached quote</b>	<b>1</b>	<b>\$486.71</b>	<b>\$486.71</b>
ITEM	QUANTITY	UNIT PRICE	TOTAL									
<b>Parts see detail in attached quote</b>	<b>1</b>	<b>\$486.71</b>	<b>\$486.71</b>									
Additional Labor Cost to Perform Repairs	<b>Labor: \$500.00</b> 5 hours each/Plumbing Rate \$100.00 per hour = \$500.00											
<b>Total Cost of Repair</b>	<b>\$986.71</b>											