

Region: 5

Location: VA002

CSS # 34398

Maximo Work Order No.: 16425

Asset #: NA

Date Issued: 02/11/22

Original Description: Need the front entry inner glass replaced. Spoke with rick about having it replaced

Repairs Needed:

S&S proposes to remove and replace the shattered front entry glass.

RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	91-1/4" X 50-1/4" TEMPERED UNIT - INSULATED UNITS CLEAR TEMPERED INSULATED/Suction cups	--	--	\$1,250.95	--	\$1,250.95
--	NA	Shipping	--	--	\$300.00	--	\$300.00
--	NA	Diagnostic	2	\$80.00			\$160.00
--	NA	Labor	20	\$80.00	--	--	\$1,600.00

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
10	\$1,760.00	\$1,550.95	NA	\$3,310.95	100%	\$3,310.95