

## Additional Funding Request

Submitted: **5/03/2021**

<b>VA002- Men's Toilet</b>	<b>CSS #TBD WO#14151</b>								
Description of Repairs	Bathroom on 1st floor was flooded from the Sloan valve sticking and the toilet being clogged so the fixture was overflowing. The Sloan was leaking from the body as well as sticking. The spud was old with the rubber damaged. Replaced both spud and Sloan valve. Pulled the fixture first to make sure the drainpipe was not clogged it was only the fixture. Reset toilet with new Sloan and tested. Work complete								
Original SC Investigative Diagnosis	NA								
Diagnosis: Initial Work Order	1St floor Men's rm toilet stopped up/ck all bathrooms to be sure working								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p><b>Materials: \$229.30</b></p> <table border="1"> <thead> <tr> <th>ITEM</th><th>QUANTITY</th><th>UNIT PRICE</th><th>TOTAL</th></tr> </thead> <tbody> <tr> <td>Parts detailed in quote</td><td>1</td><td>\$229.30</td><td>\$229.30</td></tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	Parts detailed in quote	1	\$229.30	\$229.30
ITEM	QUANTITY	UNIT PRICE	TOTAL						
Parts detailed in quote	1	\$229.30	\$229.30						
Additional Labor Cost to Perform Repairs	<p><b>Labor: \$300.00</b></p> <p>Plumbing Rate/3 hours each/Rate \$100.00 per hour = \$300.00</p>								
<b>Total Cost of Repair</b>	<b>\$529.30</b>								