

Additional Funding Request

Submitted: 9/25/2020

VA002 – DRM Board	CSS #26792 WO#12864																
Description of Repairs	Front gate is not working. It opened and had to be shut manually.																
Original SC Investigative Diagnosis	LoCurrent to replace DRM Board																
Diagnosis Fee	\$450.00																
Explanation of Additional Costs for Repairs	N/A																
Additional Material Cost to Perform Repairs	<p>Materials: \$546.00</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left;">ITEM</th><th style="text-align: left;">QUANTITY</th><th style="text-align: left;">UNIT PRICE</th><th style="text-align: left;">TOTAL</th></tr> </thead> <tbody> <tr> <td>DRM Board</td><td>1</td><td>\$546.00</td><td>\$546.00</td></tr> <tr> <td></td><td></td><td></td><td></td></tr> <tr> <td>TOTAL</td><td></td><td></td><td>\$546.00</td></tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	DRM Board	1	\$546.00	\$546.00					TOTAL			\$546.00
ITEM	QUANTITY	UNIT PRICE	TOTAL														
DRM Board	1	\$546.00	\$546.00														
TOTAL			\$546.00														
Additional Labor Cost to Perform Repairs	<p>Labor: \$450.00 1 Labor Tech/6 hours each/Rate \$75.00 per hour = \$450.00</p>																
Total Cost of Repair	\$1,446.00																