

Additional Funding Request

VA002 Room 112 Actuator	CSS # 25948 WO# 12475	July 24,2020
Description of Repairs	S&S was onsite and got both units up and running but will need an actuator for room 112. S&S will remove and replace the actuator and then complete a system check to ensure everything is running properly.	
Diagnosis: Initial Work Order CSS# 25948	The air conditioning units in rooms 110 A and 112 are not working (they are not blowing air).	
Original SC diagnosis	\$300	
Explanation of Additional Costs for Repairs	S&S was onsite and got both units up and running but will need an actuator for room 112. - S&S will remove and replace the actuator and then complete a system check to ensure everything is running properly.	
Additional Labor Cost to Perform Repairs	Labor= \$600 - 1 HVAC Tech 6 hours / \$100 an hour	
Additional Material Cost to Perform Repairs	Material= \$120.81 Actuator/ 226970- 1.00 @ \$95.81	
Total Cost	Total = \$1,020.81	