

Additional Funding Request

VA002 Boiler #1	CSS #27193 WO# 13108	October 16,2020
Description of Repairs	WO# 13108 CSS# 27193 -- Patrick and Brian from S&S mechanical found a bad draft inducer motor on #1 boiler today during boiler PM	
Diagnosis: Initial Work Order CSS# 27193	WO# 13108 CSS# pending -- Patrick and Brian from S&S mechanical found a bad draft inducer motor on #1 boiler today during boiler PM	
Original SC diagnosis	\$0	
Explanation of Additional Costs for Repairs	<ul style="list-style-type: none"> - S&S proposes to install a new draft inducer motor to replace bad motor found during the PM. 	
Additional Labor Cost to Perform Repairs	<ul style="list-style-type: none"> - 	
Additional Material Cost to Perform Repairs	S&S proposes to install a new draft inducer motor to replace bad motor found during the PM	
PM Credit	\$-250	
S&S cost	\$2,168.34	
Total Cost	Total = \$1,918.34	