

**Additional Funding Request  
From Corrective Maintenance**

Submitted 4/1/19

<b>VA002 Fan motor</b>	<b>CSS #18372 WO# 8411 Asset# 1302</b>
Description of Repairs	Air curtain by main door not working.
Diagnosis: Initial Work Order	<p>S&amp;S proposes to furnish the labor and material necessary for the completion of the following</p> <ul style="list-style-type: none"> <li>- S&amp;S will remove the old fan motor and replace with new fan motor.</li> <li>- Work will take place during normal business hours</li> </ul>
Diagnosis Fee	<b>Diagnostic Total: \$250.00</b>
Explanation of Additional Costs for Repairs	NA
Additional Labor Cost to Perform Repairs	<b>Labor: \$250.00</b> 1 HVAC Technician /2.5 hours/ Rate \$100.00 per hour = \$250.00
Additional Material Cost to Perform Repairs	<b>Material: \$353.83</b> Fan motor/PA1620/\$321.66 Tax: \$32.17
<b>Total cost</b>	<b>\$853.83</b>
<b>Minus \$250 Cost of PM</b>	\$603.83 after \$250 PM credit
Total Cost of Repair	<b>\$603.83</b>