

## **Additional Funding Request**

Submitted: 1/9/2020

<b>VA002 – gate limit switches</b>	<b>CSS #23255 WO#11568</b>								
Description of Repairs	Gate is not opening all the way on its own. Contractor has been out to adjust & now has went out due load limit switches.								
Original SC Investigative Diagnosis	NA								
Diagnosis: Initial Work Order	LoCurrent to replace limit switches on gate								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p><b>Materials: \$220.00</b></p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left;"><b>ITEM</b></th><th style="text-align: left;"><b>QUANTITY</b></th><th style="text-align: left;"><b>UNIT PRICE</b></th><th style="text-align: left;"><b>TOTAL</b></th></tr> </thead> <tbody> <tr> <td>Limit Switches</td><td>2.00</td><td>\$110.00</td><td>\$220.00</td></tr> </tbody> </table>	<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>	Limit Switches	2.00	\$110.00	\$220.00
<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>						
Limit Switches	2.00	\$110.00	\$220.00						
Additional Labor Cost to Perform Repairs	<p><b>Labor: \$600.00</b>            1 Labor Tech/8 hours/Rate \$75.00 per hour = \$600.00</p>								
<b>Total Cost of Repair</b>	<b>\$820.00</b>								