

Additional Funding Request

Submitted: 3/9/2020

| VA002 – pot feeder, filter housing | CSS #24399 WO#11973 | | | | | | | | | | | | |
|---|--|------------|----------|------------|-------|---|---|----------|----------|----------|---|---------|---------|
| Description of Repairs | Replace pot feeder and install filter system. | | | | | | | | | | | | |
| Original SC Investigative Diagnosis | NA | | | | | | | | | | | | |
| Diagnosis: Initial Work Order | Bond Water Technologies to install pot feeder as well as install filter housing off old flow line. Will clean up and dispose of old pot feeder and freight | | | | | | | | | | | | |
| Explanation of Additional Costs for Repairs | N/A | | | | | | | | | | | | |
| Additional Material Cost to Perform Repairs | <p>Materials: \$409.30</p> <table border="1"> <thead> <tr> <th>ITEM</th><th>QUANTITY</th><th>UNIT PRICE</th><th>TOTAL</th></tr> </thead> <tbody> <tr> <td>Vector FA-1000AL-TC Chemical By-pass Feeder (includes 20% markup + tax)</td><td>1</td><td>\$379.30</td><td>\$379.30</td></tr> <tr> <td>Shipping</td><td>1</td><td>\$30.00</td><td>\$30.00</td></tr> </tbody> </table> | ITEM | QUANTITY | UNIT PRICE | TOTAL | Vector FA-1000AL-TC Chemical By-pass Feeder (includes 20% markup + tax) | 1 | \$379.30 | \$379.30 | Shipping | 1 | \$30.00 | \$30.00 |
| ITEM | QUANTITY | UNIT PRICE | TOTAL | | | | | | | | | | |
| Vector FA-1000AL-TC Chemical By-pass Feeder (includes 20% markup + tax) | 1 | \$379.30 | \$379.30 | | | | | | | | | | |
| Shipping | 1 | \$30.00 | \$30.00 | | | | | | | | | | |
| Additional Labor Cost to Perform Repairs | <p>Labor: \$740.00</p> <p>Lead Project Mgr. /4 hours/Rate \$120.00 per hour = \$480.00 Asst. Tech /4 hours/Rate \$65.00 per hour = \$260.00</p> | | | | | | | | | | | | |
| Total Cost of Repair | \$1,149.30 | | | | | | | | | | | | |