

Additional Funding Request

Site: VA006	WO# 7160	CSS # 17026	Asset# NA
Description of Repairs	Boiler Needs to be Turned Back On		
Diagnosis: Initial Work Order CSS# 17026	Boiler Needs to be Turned Back On		
Explanation of Additional Costs for Repairs	Labor and material to replace Taco Circulator Pump		
Additional Labor Cost to Perform Repairs	<p>7x\$120.00=\$840.00(Incurred)</p> <p>5x\$120.00=\$600.00</p>		
Additional Material Cost to Perform Repairs	<p>Circulator Pump- \$913.29</p> <p>Shipping- \$94.77</p> <p>Trip Charge- \$55.00</p>		
Total Cost of Repair	\$1,663.06		



P.O. Box 119 • Altavista, VA 24517 • 24 Hour Service: 800.789.7199 • Fax: 888.722.2712 • MooresElectric.com

Proposal

January 15, 2019

Quotes are valid for 30 days.

USARC VA006 Charlottesville 1634 Cherry Avenue Charlottesville, VA 22903 Email	Contact Name Telephone Cell Phone Fax Number	George Grant 304-663-8670 0.00
		ggrant@internationalsupportgroup.com
		jmerchant@internationalsupportgroup.com

DESCRIPTION OF EQUIPMENT:

BOILER #2
WEIL-MCLAIN MODEL ULTRA 750,
S/N 2
CSS-17026

DESCRIPTION OF PROBLEM:

Our technician Howard Floyd checked in and was escorted to the Mechanical Room. He found Boiler #1 was off and awaiting approval for repairs. Boiler #2 was off 'Locked Out', facility had experienced a power outage this past weekend and after power was restored the boiler failed. Tech was unable to have the pad acknowledge that he was attempting to access the diagnostic screen. He repeated attempts and failed. Checked all wiring to the relays, Expansion Control, and Auto Ignition System. After accessing the diagnostics to determine the failure, he found it indicating 'off on high limit'. He checked air intake and exhaust inlet/outlets and the condensate trap on the bottom of unit; all O.K.. Reset system and boiler fired up and modulated through its heating cycle of the water. After the water had obtained temperature of 185°F tech heard a noise intermittently emanating from the circulator pump for this boiler. Suspect that the circulator pump has overheated and shut off on safety, which in turn caused the boiler to trip on high limit. Will submit a proposal for replacement of the circulator pump.

DESCRIPTION OF REPAIRS:

Isolate/drain and remove/replace the failing TACO HI-CAPACITY circulator pump. Start up and check pump operation along with boiler operation.

MATERIAL, EQUIP OR PARTS

TACO HI-CAPACITY Circulator Pump	Quantity	Sell price
Shipping	1.00	\$ 913.29
Trips Charge	1.00	\$ 94.77
	1.00	\$ 55.00
Material Total	\$	1,063.06

LABOR ITEMIZED

Labor - One Man Incurred	7	\$ 120.00	\$ 840.00
Labor - One Man	5	\$ 120.00	\$ 600.00
Labor - Second Man	0	\$ 120.00	\$ -
Labor Total		\$	600.00

Thank you for your business. If you have any questions or concerns, please feel free to contact us via telephone or quotes@mooreselectric.com

Materials	\$	1,063.06
Labor	\$	600.00

TOTAL **\$** **1,663.06**

*This does include
original call cost.*

Robert Lowery, Changeout Estimator 434-309-2591
Amy Hockaday, Estimator 434-309-2569
James Davis, Estimator 434-309-2568
Adam Barker, Estimator 434-369-3514
Jared Underwood, Estimator 434-306-2446

Approved by: _____

Standard Terms and Conditions

Payments past 30 days are subject to 1.5% monthly service charge on unpaid balance. Additional charges for payments made through credit cards may apply. Late payments sent to collections or legal process the purchaser agrees to pay all costs, expenses, and reasonable attorney fees.



HI-CAPACITY CIRCULATOR

MODEL 2400-50-3P

MAX. PRESSURE 150 PSI RPM 450


MAX WATER TEMP 110 °C 230 °F

WARNING

TO REDUCE RISK OF ELECTRICAL SHOCK SEE
INSTRUCTION MANUAL FOR PROPER INSTALLATION.
DISCONNECT POWER WHEN SERVICING. DO NOT USE
IN SWIMMING POOL AREAS. PUMP HAS NOT BEEN
INVESTIGATED FOR THIS APPLICATION.

CAUTION: FOR INDOOR USE ONLY
EMPLOYER UNIQUEMENT A L'INTERIEUR.

TACO INC. CRANSTON R.I. USA
WATER CIRCULATING PUMP



LISTED 5000C

05/18

185-063

QUOTATION

Southern Refrigeration Corporation
1620 Wythe Rd.
Lynchburg, VA 24501
434-846-6028

Order Number	
1577310	
Order Date	Page
1/15/2019 09:01:02	1 of 1

Quote Expires On 2/3/2019

Bill To:

MOORE'S ELECTRIC
PO BOX 119
ALTAVISTA , VA 24517
US

Ship To:

MOORE'S ELECTRIC
101 EDGEWOOD AVE
ALTAVISTA , VA 24517
US

Requested By: JAMES DAVIS

Customer ID: 13336

PO Number					Taker		
ISGUSARCVVA006					MMOORE		
Quantities					Item ID	Pricing	Unit
Ordered	Allocated	Remaining	UOM	Disp.	Item Description	UOM	Price

PLUS FREIGHT.

1	0	1	EA	2400-50-3P	EA	722.77	722.77
TACO CIRCULATOR							

Total Lines: 1

SUB-TOTAL: 722.77

TAX: 38.31

AMOUNT DUE: 761.08

U.S. Dollars