

Additional Funding Request

Submitted: 11/20/2020

VA011 – glycol leak	CSS #27505 WO# 13157																
Description of Repairs	WSHP#6 Unit has glycol leak CSS# 27505. Upon inspection found unit to have a glycol leak.																
Original SC Investigative Diagnosis																	
Diagnosis: Initial Work Order	Moore's will valve off system, recover glycol, repair leaking fittings, put back together and replenish glycol.																
Explanation of Additional Costs for Repairs	N/A																
Additional Material Cost to Perform Repairs	<p>Materials: \$375.00</p> <table border="1"> <thead> <tr> <th>ITEM</th><th>QUANTITY</th><th>UNIT PRICE</th><th>TOTAL</th></tr> </thead> <tbody> <tr> <td>Environmental Fee</td><td>1</td><td>\$250.00</td><td>\$250.00</td></tr> <tr> <td>Pump Fee</td><td>1</td><td>\$125.00</td><td>\$125.00</td></tr> <tr> <td>TOTAL</td><td></td><td></td><td>\$375.00</td></tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	Environmental Fee	1	\$250.00	\$250.00	Pump Fee	1	\$125.00	\$125.00	TOTAL			\$375.00
ITEM	QUANTITY	UNIT PRICE	TOTAL														
Environmental Fee	1	\$250.00	\$250.00														
Pump Fee	1	\$125.00	\$125.00														
TOTAL			\$375.00														
Additional Labor Cost to Perform Repairs	<p>Labor: \$1,500.00</p> <p>Labor incurred / 2.5 hours = \$300.00 Labor – one man / 10 hours = \$1,200.00</p>																
Total Cost of Repair	\$1,875.00																