

Date: 5-21-25

Region: 4C

FAC ID: VA012

FEMS/CSS No.: 89920

Maximo WO No.: 19155

Asset #:

Priority:  2



**Original Work Request:**

Several parking lotlights need repaired. Not working and creating a safety issue for personnel at the facility. A lift will be needed.

**Description of Repairs Needed:**

During repair, contractor noted that the lights were hardwired and a photocell was not installed. Proposal is to install a photocell that will allow lights to turn off automatically.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	1.5	\$ 150.00	\$ 225.00
Tech (1)	1.5	\$ 125.00	\$ 187.50
			\$ -

**Material List:**

	Quantity	Cost	Total
Photocell	4	\$ 59.38	\$ 237.52
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

**Equipment List:**

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$412.50	\$237.52	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$650.00	\$78.00	\$39.00	\$767.00