

Date:

Region:

CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



Original Work Request:

Install in both the male and female AMSA latrines exhaust fans with a switch.

Description of Repairs Needed:

Labor and materials to install exhaust fans and switch in both the male and female AMSA latrines.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	14	\$ 100.00	\$ 1,400.00
			\$ -

Material List:

	Quantity	Cost	Total
Flex Duct (6" x 25')	2	\$ 66.27	\$ 132.54
6" Aluminum Wall Cap	1	\$ 35.47	\$ 35.47
6" Aluminum Pipe (24" length)	2	\$ 11.49	\$ 22.98
6" Y Connector	1	\$ 46.04	\$ 46.04
Wire (12/2 Southwire SS - 250')	1	\$ 164.00	\$ 164.00
Core Bit Auger Drill	1	\$ 85.00	\$ 85.00
QTDC Series Exhaust Fan w/ Humidity Sensing	2	\$ 254.00	\$ 508.00

Equipment List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,400.00	\$994.03	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,394.03	\$287.28	\$143.64	\$2,824.96