

Date: 3-31-25

Region: 4C

FEMS/CSS No.: 96473

FAC ID: VA012

Maximo WO No.: 18504

Asset #:

Priority: 2



Original Work Request:

Rear roll up door to shop stopped working. It went up but won't come down. We had to manually get it down. Last time we had door issues the vendor said it was a sensor issue. We need this fixed ASAP.

Description of Repairs Needed:

Proposal to repair roll up door and return to proper operation.

Labor:

| | Labor Hrs | Labor Rate | Total |
|--------------|-----------|------------|-----------|
| Tech (1) | 5 | \$ 90.00 | \$ 450.00 |
| Service Call | 1 | \$ 89.00 | \$ 89.00 |
| | | | \$ - |

Material List:

| | Quantity | Cost | Total |
|--|----------|------|-------|
| | | \$ - | |
| | | \$ - | |
| | | \$ - | |
| | | \$ - | |
| | | \$ - | |
| | | \$ - | |
| | | \$ - | |

Equipment List:

| | Quantity | Cost | Total |
|--|----------|------|-------|
| | | \$ - | |
| | | \$ - | |
| | | \$ - | |

PM WO History:

| |
|--|
| |
| |

Estimate Summary:

| Labor | Material | Equipment |
|----------|----------|-----------|
| \$539.00 | \$0.00 | \$0.00 |

| Sub Total | G&A 12% | Fee 6% | Total Estimate |
|-----------|---------|---------|----------------|
| \$539.00 | \$64.68 | \$32.34 | \$636.02 |