

Date: 7-03-24

Region: 4C

CSS No.: 98269

FAC ID: VA012

Maximo WO No.: 16137

Asset #:

Priority: 2



Original Work Request:

Pot feeder that was previously installed was not properly installed or setup- it only has high pressure line and no low pressure line to circulate properly. Recommended Contractor: Casto

Description of Repairs Needed:

Proposal to troubleshoot and dianose the issues with the pot feeder. Found that the pot feeder had not been plumbed correctly by another contractor. Will follow up customer on quote to correctly plumb the pot feeder.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	8	\$ 138.00	\$ 1,104.00
Trip Charge	1	\$ 131.25	\$ 131.25

Material List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

Equipment List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,235.25	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,235.25	\$148.23	\$74.12	\$1,457.60