

Date: 4-10-25

Region: 4C

FAC ID: VA012

FEMS/CSS No.: 2966013

Maximo WO No.: 18535

Asset #:

Priority:  2



**Original Work Request:**

DHW Tank Pump (gold) not working. It was discovered on site by Casto that this pump is not working. It needs replaced. Recommended Contractor: Casto

**Description of Repairs Needed:**

Proposal is for additional work to replace HW tank circulator pump for the domestic hot water to work. After replacing DHW booster pump discovered that the circulator pump for domestic HW also needs replacing.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	4	\$ 138.00	\$ 552.00
Travel Time	4	\$ 138.00	\$ 552.00
Trip Charge	75	\$ 1.75	\$ 131.25

**Material List:**

	Quantity	Cost	Total
Model UPS26-99FC Pump	1	\$ 988.20	\$ 988.20
shipping	1	\$ 65.00	\$ 65.00
Misc parts(fittings, shop supplies...)	1	\$ 72.00	\$ 72.00
		\$	-
		\$	-
		\$	-
		\$	-

**Equipment List:**

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$1,235.25	\$1,125.20	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,360.45	\$283.25	\$141.63	\$2,785.33