

Date: 11-12-25



Region: 4C

FEMS/CSS No.: 3190166

FAC ID: VA012

Maximo WO No.: 20535

Asset #:

Priority: 2

**Original Work Request:**

During OWS inspection, contractor discovered green antifreeze inside. There hasn't been enough flow to believe that any has transferred out of the separator; however, this is urgent. The OWS has a 1000 gal capacity.

**Description of Repairs Needed:**

Proposal is to complete a laboratory analytical analysis of the impacted water in the OWS. This is for lab analysis only, a separate proposal will be provided for removal of the contents.

**Labor:**

	Labor Hrs	Labor Rate	Total
			\$ -
			\$ -
			\$ -

**Material List:**

	Quantity	Cost	Total
Laboratory Sampling/Analysis Only	1	\$ 1,200.00	\$ 1,200.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

**Equipment List:**

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

**PM WO History:**

**Estimate Summary:**

Labor	Material	Equipment
\$0.00	\$1,200.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,200.00	\$144.00	\$72.00	\$1,416.00