

Date: 7/28/25

Region: 4C

FAC ID: VA012

FEMS/CSS No.: 3219998

Maximo WO No.: 19792



Asset #:

Priority: 1

**Original Work Request:**

CO2 Alarm in Vehicle Bay is alarming/beeping.

**Description of Repairs Needed:**

Remove old CO2 sensor and replace with a new.

**Labor:**

|          | Labor Hrs | Labor Rate | Total       |
|----------|-----------|------------|-------------|
| Tech (2) | 8         | \$ 125.00  | \$ 1,000.00 |
|          |           |            | \$ -        |
|          |           |            | \$ -        |

**Material List:**

|                                               | Quantity | Cost        | Total       |
|-----------------------------------------------|----------|-------------|-------------|
| Macurco CO and NO2 Detector w Sounder (CX-12) | 1        | \$ 1,295.00 | \$ 1,295.00 |
|                                               |          |             | \$ -        |
|                                               |          |             | \$ -        |
|                                               |          |             | \$ -        |
|                                               |          |             | \$ -        |
|                                               |          |             | \$ -        |
|                                               |          |             | \$ -        |

**Equipment List:**

|  | Quantity | Cost | Total |
|--|----------|------|-------|
|  |          |      | \$ -  |
|  |          |      | \$ -  |
|  |          |      | \$ -  |

**PM WO History:**

|  |
|--|
|  |
|--|

**Estimate Summary:**

| Labor      | Material   | Equipment |
|------------|------------|-----------|
| \$1,000.00 | \$1,295.00 | \$0.00    |

| Sub Total  | G&A 12%  | Fee 6%   | Total Estimate |
|------------|----------|----------|----------------|
| \$2,295.00 | \$275.40 | \$137.70 | \$2,708.10     |