

Date: 9-30-25



Region: 4C

FEMS/CSS No.: 3220200

FAC ID: VA012

Maximo WO No.: 20322

Asset #:

Priority: 1

Original Work Request:

Find peripheral troubles with the fire monitoring panel in AMSA shop.

Description of Repairs Needed:

Replace multiple CO/smoke detectors causing trouble light on fire panel

Labor:

	Labor Hrs	Labor Rate	Total
Tech(1)	8	\$ 150.00	\$ 1,200.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
Siemens Combo Smoke/CO Detector (FD00TC441)	10	\$ 285.00	\$ 2,850.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,200.00	\$2,850.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$4,050.00	\$486.00	\$243.00	\$4,779.00