

Date: 2-09-26



Region: 4C

FEMS/CSS No.: 3220200

FAC ID: VA012

Maximo WO No.: 21222

Asset #:

Priority: 1

**Original Work Request:**

Find peripheral troubles with the fire monitoring panel in the AMSA shop.

**Description of Repairs Needed:**

Proposal are to replace two remaining smoke/CO detectors in the ceiling of the AMSA Shop. Detectors are already paid for under WO 20327.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (2)	8	\$ 137.50	\$ 1,100.00
			\$ -
			\$ -

**Material List:**

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

**Equipment List:**

	Quantity	Cost	Total
40" Boom Lift	1	\$ 1,320.00	\$ 1,320.00
			\$ -
			\$ -

**PM WO History:**

**Estimate Summary:**

Labor	Material	Equipment
\$1,100.00	\$0.00	\$1,320.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,420.00	\$290.40	\$145.20	\$2,855.60