

Date: 7-25-25

Region: 4C

FAC ID: VA012

FEMS/CSS No.: 3265505

Maximo WO No.: 19789



Asset #:

Priority: 1

Original Work Request:

The overhead cranes do not have a current weight test on file. The 10 ton overhead crane needs to be weight tested and documented to pass inspection

Description of Repairs Needed:

Perform certified load test and provide weights and rigging as needed for the load test of (1) 10 ton overhead crane and hoist. Also complete repair of the pendent plug connector and wire.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	16	\$ 125.31	\$ 2,005.00
Trip Charge	1	\$ 75.00	\$ 75.00
			\$ -

Material List:

	Quantity	Cost	Total
Service Test Truck, Weight Buggy, Rigging	1	\$ 2,293.00	\$ 2,293.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
Scissor Lift	1	\$ 1,405.00	\$ 1,405.00
Fork Lift	1	\$ 479.00	\$ 479.00
			\$ -

PM WO History:

--

Estimate Summary:

Labor	Material	Equipment
\$2,080.00	\$2,293.00	\$1,884.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$6,257.00	\$750.84	\$375.42	\$7,383.26