

Date: 3-13-24

Region: 4C

CSS No.: 91672

FAC ID: VA033

Maximo WO No.: 15240

Asset #:

Priority: 3



**Original Work Request:**

The handicap latrine toilet is continuously running after it has been flushed.

**Description of Repairs Needed:**

Replace Urinal Flushometer that is currently not operating as designed.

**Labor:**

|          | Labor Hrs | Labor Rate | Total     |
|----------|-----------|------------|-----------|
| Tech (1) | 2         | \$ 100.00  | \$ 200.00 |
|          |           |            | \$ -      |

**Material List:**

|  | Quantity | Cost      | Total     |
|--|----------|-----------|-----------|
| Sloan Royal Urinal Flushometer ( 1.0 GPF, 3012636) | 1        | \$ 172.00 | \$ 172.00 |
|  |          | \$        | -         |
|  |          | \$        | -         |
|  |          | \$        | -         |
|  |          | \$        | -         |
|  |          | \$        | -         |
|  |          | \$        | -         |

**Equipment List:**

|  | Quantity | Cost | Total |
|--|----------|------|-------|
|  |          | \$   | -     |
|  |          | \$   | -     |
|  |          | \$   | -     |

**PM WO History:**



**Estimate Summary:**

| Labor    | Material | Equipment |
|----------|----------|-----------|
| \$200.00 | \$172.00 | \$0.00    |

| Sub Total | G&A 12% | Fee 6%  | Total Estimate |
|-----------|---------|---------|----------------|
| \$372.00  | \$44.64 | \$22.32 | \$438.96       |