

Date: 1-17-25

Region: 4C

FAC ID: VA033

FEMS/CSS No.: 2966447

Maximo WO No.: 17923

Asset #:

Priority: 2



Original Work Request:

BFP failed...the report states that the check valve #2 leaked. Replace backflow preventer. Recommended: Joseph Monaco (571) 332-0719 or Sean Spain (443) 561-6501

Description of Repairs Needed:

Proposal is to replace the backflow preventer (M#975X; S# 921338). Note: Proposal is for installation of BFB only, customer will need provide someone to certify the unit.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	8	\$ 138.00	\$ 1,104.00
Trip Charge	90	\$ 1.75	\$ 157.50
			\$ -

Material List:

	Quantity	Cost	Total
975LF-7 Wilkin 3/4" 975xXL2 BFP	1	\$ 528.37	\$ 528.37
shipping	1	\$ 52.00	\$ 52.00
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,261.50	\$580.37	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,841.87	\$221.02	\$110.51	\$2,173.41