

Date: 1-29-25

Region: 4C

FAC ID: VA033

FEMS/CSS No.: 2966449

Maximo WO No.: 17970



Asset #:

Priority: 3

Original Work Request:

Exhaust fan (asset 3531) not working

Description of Repairs Needed:

Replace exhaust fan

Labor:	Labor Hrs	Labor Rate	Total
Tech (1)	4	\$ 100.00	\$ 400.00
			\$ -
			\$ -

Material List:	Quantity	Cost	Total
Downblast Roof Exhaust Fan (#16D527)	1	\$ 440.00	\$ 440.00
Fire Stop Caulk (CP 25WB)	1	\$ 14.98	\$ 14.98
shipping	1	\$ 50.00	\$ 50.00
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$400.00	\$504.98	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$904.98	\$108.60	\$54.30	\$1,067.88