

Date:

Region:

CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



Original Work Request:

NO HEAT, this PTAC is not working and this room becomes especially cold. The unit is pushing air just no heat or AC

Description of Repairs Needed:

Investment is to replace/install non-working PTAC with new unit.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	8	\$ 132.00	\$ 1,056.00
Trip Charge	150	\$ 1.75	\$ 262.50

Material List:

	Quantity	Cost	Total
PTAC - M312HP3ZX Sea Breeze H/P PTAC - United	1	\$ 1,508.56	\$ 1,508.56
Shipping & Handling	1	\$ 162.50	\$ 162.50
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,318.50	\$1,671.06	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,989.56	\$358.75	\$179.37	\$3,527.68