

## Additional Funding Request

<b>Site: VA048</b>	<b>WO#7186</b>	<b>CSS # 17099</b>	<b>Asset# NA</b>
Description of Repairs	Surveillance Monitors INOP		
Diagnosis: Initial Work Order <b>CSS# 17099</b>	Replace Surveillance Monitors		
Explanation of Additional Costs for Repairs	Labor and material to replace surveillance monitors		
Additional Labor Cost to Perform Repairs	3 x \$80.00- \$240.00		
Additional Material Cost to Perform Repairs	\$672.00		
Total Cost of Repair	\$912.00		



(804) 276-7300  
3513 Gregory Pond Road  
North Chesterfield, VA 23236

# Proposal

Date: 1/23/2019

Proposal No: 1089

To: International Support Group  
9000 Sheridan St Suite 172  
Pembrok Pines, FL 33024

Job Reference	Terms
Troy	CC

Approved By: \_\_\_\_\_ Date \_\_\_\_\_

\* Phone (804) 276-7300

\* Fax (804) 276-6714

\* [www.qualitycctv.net](http://www.qualitycctv.net)