

Over and Above Estimate

Region: 5

Location: VA049

CSS # 21023

Maximo Work Order No.: 11047

Date Issued: 9/19/19

Original Description: Madison Taylor Indoor Environmental to perform mold inspection analysis and remediation scope of work. Madison Taylor Services guarantees to perform the mold remediation process according to the industry accepted guidelines contained in IICRC S520, NYC Guidelines and EPA Standards. The procedures required for this contract are defined further in the Explanation of Remediation portion of this proposal.

Non Pre-Priced Estimate:

Quantity	Line Item Number	Description	Labor Hours	Tax Ship	Labor	Materials	Equipment	Total
1	N/A	Remediation Costs – See page 14 (C-2) & 15 (C-3) of proposal for details on scope of remediation and pricing						34,002.00

Note: RS Means (Pre-Priced) not used in compiling this estimate.

Note: Subcontractor quote attached.

Estimate Summary:

Labor Hours	Labor Cost	Material Cost		Total Cost	CE Factor	Total Estimate
	\$	\$		\$34,002.00	106%	\$36,042.12

CMI will do this for the customer as a pass through. CMI takes no responsibility or liability for the mold remediation as mold remediation is not in our contract. This vendor was supplied by the customer as the preferred vendor which included the report and pricing. Scott Grenier will handle all scheduling.