

Tina Lee

From: Richard Hicks
Sent: Thursday, July 14, 2022 3:51 PM
To: Tina Lee
Subject: FW: VA049 Update

From: Richard Hicks
Sent: Thursday, July 14, 2022 1:55 PM
To: Shara Fortier <Shara.Fortier@tideh2o.net>; Mary Lowery <Mary.Lowery@tideh2o.net>; Adam Colopy <adam.colopy@tideh2o.net>; Moronez, Antonio G CIV USARMY 99 RD (USA) <antonio.g.moronez.civ@army.mil>; christopher.p.chipps.ctr@army.mil; Devlin, Thomas J CIV USARMY CENAP (US) <Thomas.J.Devlin@usace.army.mil>
Cc: Earl Ware <eware@mooreselectric.com>; Jonathan Locy <jlocy@moorehvacr.com>
Subject: VA049 Update

Tony , Team ,
I have received Verbal approval from Tom to proceed with repairs at VA049 . **Earl, please use this approval .**
The chiller circuit #2 is operational -Moore's is cleaning the coil for circuit #2

What needs to be repaired

1. Chiller / CURNIT #1 Temp and transducer sensor needs to be replaced
2. AHU #2 drive line bearings have failed and need to be replaced --AHU OUT OF SERVICE UNTIL REPAIRS ARE COMPLETED
3. Shara , Earl – I need formal proposals ASAP .

Work Order	Description	Site
18472	HVAC is not cooling and is making a loud unusual noise.	99REG

Thanks,
Rick
Rick Hicks
Project Manager Region 5
CMI Management Inc.
5285 Shawnee Road Suite #510
Alexandria,VA 22312
703-738-5301
Richard.Hicks@cmimgmt.com