

## Additional Funding Request

Site: VA049	CSS # 13465      WO-6003
Description of Repairs	Replace 75 ea blown out light bulbs (T8), replace 20 ea U shape, 6 ea in arms room.
Diagnosis: Initial Work Order <b>CSS# 13465</b>	Replace 75 ea blown out light bulbs (T8), replace 20 ea Ushape, 6 ea in arms room.
Explanation of Additional Costs for Repairs	Labor and material to complete call
Additional Labor Cost to Perform Repairs	\$80x8= \$640
Additional Material Cost to Perform Repairs	\$ 563.46
<b>Total of CSS ticket (Excluding) Service call cost OF \$172.50</b>	\$
Total Cost of Repair	\$ 1,203.46