

Additional Funding Request

Site: VA049	WO# 8821	CSS # 18809	Asset# NA
Description of Repairs	Need to investigate leak at bottle filler station		
Diagnosis: Initial Work Order CSS# 18809	Leak at bottle filler station		
Explanation of Additional Costs for Repairs	Labor to investigate and possible repair leak at bottle filler station		
Additional Labor Cost to Perform Repairs	$6 \times \$120.00 = \720.00		
Additional Material Cost to Perform Repairs	\$55.00 (Truck Fee)		
Total Cost of Repair	\$775.00		



P.O. Box 119 • Altavista, VA 24517 • 24 Hour Service: 800.789.7199 • Fax: 888.722.2712 • MooresElectric.com

Proposal

June 14, 2019

Quotes are valid for 30 days.

VA049 - CHESTERFIELD
3700 Strathmore Road
N. Chesterfield, VA 23237
Email

Contact Name
Telephone
Cell Phone
Fax Number
ggrant@internationalsupportgroup.com
tcaig@internationalsupportgroup.com

George Grant
304-663-8670

DESCRIPTION OF EQUIPMENT:

CSS 18809 - Water Fountain Leak

DESCRIPTION OF REPAIRS:

Moore's proposes to investigate leak in between the walls being caused by water fountain per customer's request.

MATERIAL, EQUIP OR PARTS

	Quantity	Sell price
Truck Fee	1.00	\$ 55.00
		Material Total \$ 55.00

LABOR ITEMIZED

	6		Labor
Labor - One Man		\$ 120.00	\$ 720.00
		Labor Total	\$ 720.00

Thank you for your business. If you have any questions or concerns,
please feel free to contact us via telephone or quotes@mooreselectric.com

Materials	\$ 55.00
Labor	\$ 720.00

TOTAL	\$ 775.00
--------------	------------------

Robert Lowery, Changeout Estimator 434-309-2591
Amy Hockaday, Estimator 434-309-2569
James Davis, Estimator 434-309-2568
Adam Barker, Estimator 434-369-3514
Jared Underwood, Estimator 434-306-2446

Approved by: _____

Standard Terms and Conditions

Payments past 30 days are subject to 1.5% monthly service charge on unpaid balance. Additional charges for payments made through credit cards may apply. Late payments sent to collections or legal process the purchaser agrees to pay all costs, expenses, and reasonable attorney fees.