

## Additional Funding Request

<b>Site: VA049</b>	<b>WO# 8823      CSS # 18882      Asset# NA</b>
Description of Repairs	Replace Lock
Diagnosis: Initial Work Order <b>CSS# 18882</b>	Replace Lock on Door 132E
Explanation of Additional Costs for Repairs	Labor and material to replace lock
Additional Labor Cost to Perform Repairs	2 x \$80.00= \$160.00
Additional Material Cost to Perform Repairs	\$522.78
Total Cost of Repair	\$682.78

KABA

# Mechanical Push Button Lockset, 5 Button, Vandal Resistant, Entry, Satin Chrome

Item # **SU742** Mfr. Model # **LR-1011-26D-41** Catalog Page # **1974** UNSPSC # **46171503**



Web Price ⓘ  
**\$435.65** / each

☒ One Time Delivery

1

Add to Cart

[+ Add to List](#) |

☒ Shipping

☐ Picku

Expected to arrive **Wed. May 29**

Ship To **32003** [\(Change\)](#)

Jump to:

[Replacement Parts](#)

☆☆☆☆☆ [Be the first to write a review](#)

Shipping Weight **8.7 lbs.**

[How can we improve our Product Images?](#)

☐ Compare

Country of Origin **Mexico** | *Country of Origin is subject to change.*

*Note: Product availability is real-time updated and adjusted continuously. The product will be reserved for you when you complete your order. [More](#)*

## Product Details

Single-code lock has a selectable classroom/storeroom function that provides code-free egress. Lock requires no batteries, computers, or [View More](#) ▾

## Technical Specs

Item	Mechanical Push Button Lockset	Series	L1000
Handle Type	Lever	Outside Height	7-3/8"
Function	Entry	Outside Width	3-1/8"
Key Override Options	None	Outside Depth	3-13/16"
Hand	Right	Inside Height	9"
Finish	Satin Chrome	Inside Width	3-1/4"
Door Thickness	1-3/8" to 2-1/4"	Inside Depth	2-3/8"
Keypad	5 Button, Vandal Resistant	Latch Length	1/2"
Backset	2-3/4"	Max. User Codes	1
ADA Compliant	Yes	Standards	ANSI 156.2
Fire Rated	3 hr.	Weather Resistant	Yes
Case Material	Zinc	Includes	Lock, Template, Manual, Required Installation Hardware, Code Change Plug and Access Key