

Additional Funding Request

Site: VA099	WO# 10604	CSS # 20784	Asset# NA
Description of Repairs	VA099 needs dail lock replacement. The 99th has switched all locks over to the S&G 2937 for vaults.		
Diagnosis: Initial Work Order CSS# 20784	Lock damaged, it will be completely broke soon		
Explanation of Additional Costs for Repairs	Labor and material to replace lock		
Additional Labor Cost to Perform Repairs	$8 \times \$93.75 = \$750.00 + \$250.00$ Trip Charge		
Additional Material Cost to Perform Repairs	\$860.00		
Total Cost of Repair	\$1,860.00		

ADVANCED SECURITY SAFE & LOCK
6318 REISTERSTOWN RD
BALTIMORE, MD 21215

Tel: (410) 764-2001
Tel: (877) 267-6562
Fax: (410) 561-6031
Email: Billing2@ampmlock.com
www.AMPMLOCK.com



Estimate

Date	Estimate #
7/30/2019	28954

Customer Information
CMI Management Rick Hicks 5285 Shawnee Road Suite 510, Maryland 22312

Item	Description	Qty	Cost	Total
S&G Dail Lock	VA099 needs dail lock replacement. The 99th has switched all locks over to the S&G 2937 for vaults. S&G 2937 list price- 713.00	1	860.00	860.00
LABOR	Labor to install lock 8 hours standard rate for chaning out dail lock.	1	750.00	750.00
SERVICE CALL	Service Call down to Southern VA.	1	250.00	250.00

WE LOOK FORWARD TO ASSISTING YOU!

Advanced Security Safe & Lock's One Year Warranty on recalls only covers parts and services/labor when the part is provided by Advanced Security Safe & Lock. Service/labor on parts not provided by Advanced Security Safe & Lock or if the parts have passed the one year warranty time period are NOT covered under Advanced Security Safe & Lock's One Year Warranty.

SIGNATURE: _____

DATE: _____

Terms: 50% deposit and 50% due upon completion

Subtotal	\$1,860.00
Sales Tax (0.0%)	\$0.00
Total	\$1,860.00