

CERTIFICATION OF WORK PREVENTIVE MAINTENANCE

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY067 Date of Visit: 11-20-18

Contractor Personnel on Site:

1. Patrick Brown
2. _____
3. _____
4. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. 1010 MO, 1119 QT, 1120 QT, 1121 QT, 1122 QT, 1123 QT, 1124 QT, 1125 QT, 1126 QT
2. 1127 QT, 1128 QT, 1129 QT, 1130 QT
3. Motor Vehicle Area Light, Chill Water Pump, Hot Water Pump, Freezer, Fridge, Ice Maker
4. Emergency Light, Water Heater, Emergency Light, Emergency Exit Sign
5. _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Patrick Brown Date: 11-20-18

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Douglas Rushko Date: 11/20/18

Signed: 

E-Mail: douglas.rushko.dns@mail.mil

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST
LIGHTING, OUTSIDE

SITE AND BLDG #: NY067 - Bldg 1

LOCATION/RM #: Motor Vehicle Area WO# 1010 ASSET # 10612

MECHANIC
SIGNATURE:

DATE: 11-20-18

START TIME: 9 AM

FINISH TIME: 9:45 AM

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)
		YES	NO	
SPECIAL INSTRUCTIONS				
1	In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered to.	✓		
2	Schedule and coordinate work with operating personnel.	✓		
3	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.	✓		
TO BE PERFORMED AT EACH INSPECTION SERVICE				
1	Open and tag switch.	✓		
2	Inspect visual condition of wiring. Look for evidence of overheating.	✓		Wires are Brand New
3	Check for proper light operation.	✓		Poles & lights have not arrived on sight yet
4	Test operation of automatic switches/ time clock/ photocells if applicable.	✓		()
5	Inspect light pole and mounting devices for deficiencies.	✓		Mount are Brand New. Poles are not on sight yet
6	For any noted deficiency, takes pictures and open corrective maintenance ticket.	✓		Waiting for new poles to be installed; Poles and lights have already been contracted out

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

To be performed by: General Maintenance Worker

Additional Notes: