

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 3-9-23 ARRIVAL TIME 8:00 DEPARTURE TIME 12:00 JOB/TCK. NO. 191366CUSTOMER P.O. NO. CSS# 90952JOB NAME/LOCATION USARC - MG Guy B Denit VA039SERVICE REQUESTED (12) Investment is labor and material to replace the control module and wiring harness on the Prestige Triangle Tube

Manufacture: <u>Other</u>				
Model#: <u>SOLO399</u>				
Serial#: <u>PS80240</u>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested☐ Leak Found☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Arrived on site, checked in with customer. Went to boiler room and took panel off boiler number 4. Put the control board in then hooked it up. Then cut the wiring harness off where the wire was broke. Put butt connectors on the ends and then put the new harness on to the other side of the butt connectors. Once i got everything hooked up i turned power on and when the combustion fan kicked on it was out of balance. I took the combustion fan housing out and found that the mounting bracket for it was messed up. Then i went out side and tried to cut some rubber spacers for it to get it to balance out but that did not work either. Got the info off the boiler and going to quote to replace the combustion fan assembly. Packed up tools and put them away. Then

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

QTY.	PART NO.	DESCRIPTION	P.L.	VENDOR	
1		Shipping & Handling		Ferguson	226677
1		Sp-TPSCONN10 WIRING HARNESS		Ferguson	226677
1		Sp-TPKIT50 CONTROL MODULE		Ferguson	226677

SUMMARY OF TIME

SERVICE TECHNICIAN	ON SITE REG.	ON SITE O.T.	REG. TRAVEL	O.T. TRAVEL	TOTAL HRS.	MEALS	LODGING	TOLLS	MILES	OTHER
1154 Shawn Shelton	4		3		7					

JOB COMPLETE YES X NO _____ EXPLAIN but boiler is still not running

SIGNATURE _____

Customer Representative

SERVICE REPORT

CUSTOMER P.O. NO. CSS# 90952

SERVICE REQUESTED *Boiler #4 (S# PS80240). 11741*

Manufacture: <i>Other</i>				
Model#: <i>SOLO399</i>				
Serial#: <i>PS80240</i>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: _____

Total Charge: _____

done paper work.

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

[illegible][illegible]

SIGNATURE _____

Customer Representative