

**CERTIFICATION OF WORK
PREVENTIVE MAINTENANCE**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: DE001 Date of Visit: 9/3/20

Contractor Personnel on Site:

1. <u>John Brown</u>	3. _____
2. _____	4. _____

Work Performed:


Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO 12619FQ,12641MO,12691PMA,12718PMF,12729PMQ,12734PMS
2. 12620FQ,12692SA, 12719PMF,12735PMS
3. FILTERS,LIGHTILING,MINI SPLIT, HAVA CONTROL PANEL,
4. CHEMICAL POT FEEDEREXPANSION TANKS,WALL PACKS,
5. _____

CERTIFICATION OF WORK

To be signed by the Contractor:


Print Name: Johnny W Brown Date: 9/3/20

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Trecka Derilus Date: 9/3/20

Signed: 

E-Mail: _____

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST
DUCTLESS MINI SPLIT

SITE AND BLDG #: **DE001-01**MECHANIC
SIGNATURE: DATE: **9/3/20**LOCATION/RM #: **WO# 12691 ASSET # 1689**START TIME: **0900** FINISH TIME: **1630**

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)
		YES	NO	
SPECIAL INSTRUCTIONS				
1	As needed, de-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work. Follow lock out/tag out procedures at all times.	/	/	
TO BE PERFORMED AT EACH INSPECTION SERVICE				
1	Check fan blades for dust buildup and clean if necessary.	/	/	
2	Check all electrical connections	/	/	
3	Check that the fan runs properly in all speeds as applicable.	/	/	
4	Check dampers and rotating auto diffusers for dirt accumulations, clean as necessary.	/	/	
5	Check filter door for proper gasketing and air leaks. Correct as needed.	/	/	
6	Change or Clean filter as needed. Filters get checked quarterly.	/	/	
7	Ensure condensate pump is working properly and that the drain lines are clear.	/	/	
8	Clean up work area.	/	/	

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

To be performed by: General Maintenance Worker

Additional Notes: