

FW: VA049 and VA050 Update

Richard Hicks <richard.hicks@cmimgmt.com>

Mon 12/21/2020 9:12 AM

To: Brenda Gerold <brenda.gerold@cmimgmt.com>

Tina upload email to wo# 13300

Rick

From: Avner Shots <avner@ampmlock.com>

Sent: Wednesday, December 16, 2020 10:30 AM

To: Richard Hicks <richard.hicks@cmimgmt.com>

Cc: Limor Gholian <limor@ampmlock.com>

Subject: VA049 and VA050 Update

Good Morning Rick,

Hope you are enjoying vacation.

Update:

The Battery back up for VA050 is complete

VA049 - Only one x-10 was successfully installed yesterday on the safe. The other 2, x-10s for the vaults need to be modified and machined in our shop and on site to install. We need to re quote this job for a return trip.

Couple things to note:

1) The safe which the x-10 was installed in had been drilled previously and is not up to GSA certification. However now the x-10 is more secure than the previous lock.

2) The 2 vault doors are Schwab Vault doors and now discontinued. They are not currently up to GSA certification and shop time will be needed to extend the bolt and modify to properly install. However will not make the Vault GSA certified.

Please let me know if you have any questions and advise on how to proceed.

Thanks

Best Regards,

Avner Shotz



Office: [\(410\) 764 2001](tel:(410)7642001)
Email: Avner@ampmlock.com
Website: www.AMPMLOCK.com
6318 Reisterstown Rd
Baltimore, MD 21215

Small Business Enterprise
Woman Owned Small Business

