

Region: 5

Location: MD002

CSS #: NA

Maximo Work Order No.: 16944

Asset #: NA

Date Issued: 4/27/22

Original Description: Problem: Gas leak on the exterior of the building, 2" steel gas line.

S&S found (3) gas valves that were leaking all located in close proximity.

S&S will perform an exploratory dig to understand how they are piped and where the leaks are located.

Repairs Needed:

Problem: Gas leak on the exterior of the building, 2" steel gas line.

S&S found (3) gas valves that were leaking all located in close proximity.

S&S will perform an exploratory dig to understand how they are piped and where the leaks are located.

RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	Materials (See attached Detail)	--	--	--	--	--
--	NA	S&S Labor (includes Diagnostic)	38	\$100.00	--	--	\$3,800.00
--	NA	TW Coordination Labor	--	--	--	--	--

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
38	\$3,800.00	--	--	\$3,800.00	106%	\$4,028.00



CUSTOMER QUOTATION NO. 1016

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Quote Name: 16944
Quote No: 1016
Site: MD002 Ordnance Road
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 04/27/2022
Valid For: 30 Day(s)

WO#: 16944

CSS Ticket Number: Pending

Problem: Gas leak on the exterior of the building, 2" steel gas line.

S&S found (3) gas valves that were leaking all located in close proximity.

S&S will perform an exploratory dig to understand how they are piped and where the leaks are located.

Service

Item	Quantity	Unit Price	Total
Diagnosis Fee	1	\$1,800.00	\$1,800.00
Labor	1	\$2,000.00	\$2,000.00
		Sub-Total ex Tax	\$3,800.00
		Tax	\$0.00
		Total inc Tax	\$3,800.00

Labor	\$3,800.00
Sub-Total ex Tax	\$3,800.00
Tax	\$0.00
Total inc Tax	\$3,800.00