

**CERTIFICATION OF WORK
PREVENTIVE MAINTENANCE**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY039 Date of Visit: 6/21/22

Contractor Personnel on Site:

1. Patrick Brown 3. _____
2. _____ 4. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO#'S , 17355 , 17356 , 17377 , 17378 , 17550-17555 ,
2. 17559 , 17568 , 17574 , 17593 , 17407 , 17556 , 17594 ,
3. 17595 ,
4. ASSET#'S , 9891 , 9896 , 9932 , 9935 , 9893-9897 , 9931 ,
5. 9943 , 9939 , 190917- , 245 , 269 , 264 , 267 , 270 , 274 ,
275

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Patrick Brown Date: 6/21/22

Signed: 

To be signed by Facility Manager:


By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Gysgt elwart Date: 6/21/22

Signed: 

E-Mail: _____

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST
SUMP PUMP

SITE AND BLDG #: **NY039 BLDG1**MECHANIC
SIGNATURE: DATE: **6/21/22**

boiler room

LOCATION/RM #:

WO# **17574**ASSET #**190917-264**START TIME: **12:30pm**FINISH TIME: **1pm**

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)
		YES	NO	
SPECIAL INSTRUCTIONS				
1	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
2	Excessive sediment and debris, not removed by flushing the pit should be handled on a project basis, and not considered under this standard.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
TO BE PERFORMED AT EACH INSPECTION SERVICE				
1	Remove cover plates and flush pit.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	pit is clear
2	Inspect check valve.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	check valve functions properly
3	Inspect interior of pit for cracks.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	no cracks
4	Inspect cover plate is in place	<input checked="" type="checkbox"/>	<input type="checkbox"/>	cover plate is good
5	Insuure the unit is operating properly, report any deficiencies	<input checked="" type="checkbox"/>	<input type="checkbox"/>	unit functions properly
6	Clean up work area and remove all debris.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed discription of the deficiency.

To be performed by: General Maintenance Worker

Additional Notes: