

SAFETY NOTIFICATION

KONECRANES®
Lifting Businesses™

Report Created: Jun 25, 2019 9:28 AM

Customer and Service Information

Customer	Tidewater Inc / US Army Reserve - New Castle		
Business Location	US Army Reserve - New Castle, New Castle, 410 Miller Ave		
City	New Castle		
Agreement	U240- US Army Reserve - New Castle		
Service Request	1-89540771178		
Description	PIT - June 2019 Mainman Assessment with Routine Maintenance		
PO Number	Karlee Demain		
Billing Type	Fixed		
Customer Contact	Karlee Demain	Konecranes Contact	Thomas Yakich 4127879480 tom.yakich@konecranes.com
	karlee.demain@tideh2o.net		

Assets

 001	Custom Structure - Monorail 1 Trolley 1 Electric Wire Rope Hoist		
Criticality	Moderate	Span	28ft
Site Location	TRUCK MAINTENANCE SHOP / UPPER BUILDING 2	Lift	15ft
Capacity/SWL	5 Ton	Volt/Ph/Hz	208-3-60
Service Products	Routine Maintenance, MAINMAN Assessment		

! Markings	Quote
Date Reported	Jun 25, 2019
Technician	Shawn Harrity
Task Type	Visual assessment
Fault Code	Missing
Risk	Safety Risk
Recommendation	Replace
Comment: Capacity markings on one side of monorail only.	

Trolley

Hoisting machinery Info	Quote
! Hoisting wire rope	
Date Reported	Jun 25, 2019
Technician	Shawn Harrity
Task Type	Visual assessment
Fault Code	Bent, damaged
Risk	Safety Risk
Recommendation	Replace
Comment: Hoist wire rope was damaged strands. In several areas. Recommend replacement of the wire rope.	

Electrics

SAFETY NOTIFICATION

KONECRANES®
Lifting Businesses™

Control system

✓ Hoisting limit switches

Date Reported

Jun 25, 2019

Repaired

Technician

Shawn Harrity

Task Type

Visual assessment

Fault Code

Trip device damaged

Risk

Safety Risk

Recommendation

Replace

Comment:

Readjusted the trip arm. Test ran several times. To make shore the adjustment was correct.

All tests are good. Returned the asset to service.

Reason for repair:

Weighted upper limit trip arm contacts hoist frame. Limit does not trip properly.



Jun 25, 2019 9:17 AM Karlee Demain, Customer



Jun 25, 2019 9:19 AM Shawn Harrity, Technician

Component Condition

- ✓ Acceptable (No issues detected)
- ! Need Attention

Findings and Actions

Safety Risk **WARNING**

Indicates an unsafe condition. Failure to remedy such condition before continued operation of the identified Asset may result in personal injury including death, or property damage.

Acceptable / Repaired Item

Component condition is verified by Konecranes service technician. No actions required. If a component or other object has been repaired within the service visit, green color code is shown as well.

KONECRANES® STORE

SPARE PARTS, ACCESSORIES AND SELECT
PRE-CONFIGURED LIFTING EQUIPMENT

store.konecranes.com

ONLINE
ANY TIME

YOURKONECRANES

CRANE MAINTENANCE INFORMATION
AND REMOTE MONITORING DATA

your.konecranes.com

CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

INSPECTION, TESTING, AND CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: US Army Reserve - New Castle Date of Visit: 7-25-19

Contractor Personnel on Site:

1. <u>Shawn Harrity</u>	4. _____
2. _____	5. _____
3. _____	6. _____


Work Performed:

Inspection, Testing, and Certification

1. Annual Crane Testing
2. Asset# 6916 WO# 9068 & 9180
3. _____
4. _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Tom Yakich (Maintenance Planner) Date: 7-21-19
Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Cynthia Croyle Date: 7/03/2019
Signed: 
E-Mail: _____