

W0 93506
IW 94393

CNI 05519293
W0 4099

ATTACHMENT J-0200000-05
FORMS

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: Plattsburgh Date of Visit: 6/7/19

Contractor Personnel on Site:

1. _____
2. _____
3. _____
4. _____
5. _____
6. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. _____
2. _____
3. N/A
4. _____

Inspection, Testing, and Certification

1. _____
2. _____
3. N/A
4. _____

Other Recurring Services

1. _____
2. _____
3. N/A
4. _____

Service Calls - Service Call Number and Description

1. repair / clean heat exchanger - Diagnostic
2. Bluted repair - See page 2 for
3. work description

ATTACHMENT J-0200000-05
FORMS

Over and Above Repair Work – Order Number and Description of Work Completed

Diagnostic

Employee /	Subject /	
Date	Properties	Text
6/7/2019	HOWARD; DOUGLAS E.	Work Performed
CustView		Need lift to make repairs found small fan coil in gym room leaking from union Recommend replacing two 1.25 unions and two 1.25x 3-6

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Tammy Parisian Date: 8/29/19
Signed: Tammy Parisian

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: See attached Date: _____
Signed: _____
E-Mail: _____



**Hyde-Stone
Mechanical
Contractors**

SERVICE REPORT

WORK ORDER:

93506

CUSTOMER PO: 4099

DATE: 06/07/2019

CUSTOMER: US ARMY RESERVE - PL (AR#:10343)
STREET: 5363 PERU STREET, ROUTE 9
CITY: PLATTSBURGH, NY 12901
CONTACT: RON VOGT - CELL

DESCRIPTION: WO#4099/ CSS19293/ NY054 Plattsburg usarc repair heat exchanger needs to be cleaned / CMI// CMI CONTACT VANESSA FERNANDEZ 703-738-5306
CALL TYPE: PLATTSB - AIR CONDITIONING
TROUBLE REPORTED: PL - AIR CONDITIONING
WORK PERFORMED: Need lift to make repairs found small fan coil in gym room leaking from union. Recommend replacing two 1.25 unions and two 1.25x 3-6 (HOWARD; DOUGLAS E. on Jun 7, 2019)

PARTS		DESCRIPTION
QUANTITY		
1	VEHICLE CHARGE	

LABOR		
DATE	LABOR	TECHNICIAN/DESC
06/07/2019	1.5 (PW-REG)	HOWARD; DOUGLAS E. (Service Repair)

IS JOB COMPLETE? **No**

Customer

Name:

Date: 06/07/2019 10:40 AM

Comments:

Email

Customer Signature

Employee Signature

Employee

Name: DOUG HOWARD

Date: 06/07/2019 10:40 AM

Comments: