

WW * 93613
IN * 95417

CSS * 19293
WW * 4099

ATTACHMENT J-0200000-05
FORMS

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: Plattsburgh Date of Visit: 7/19/19

Contractor Personnel on Site:

1. _____
2. _____
3. _____
4. _____
5. _____
6. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. _____
2. _____
3. N/A
4. _____

Inspection, Testing, and Certification

1. _____
2. N/A
3. _____
4. _____

Other Recurring Services

1. _____
2. N/A
3. _____
4. _____

Service Calls – Service Call Number and Description

1. quoted repair of leak in fan coil in the gym.
2. see page 2 for description.
3. _____

ATTACHMENT J-0200000-05
FORMS

Employee / Date	Subject / Properties	Text
7/19/2019 HOWARD; DOUGLAS E.	CustView	Work Performed Drained line and unsolder joints on top and bottom of heater. Removed rusted out dielectric fittings. Installed new air vent and boiler drain cap. Solder in new unions and checked for leaks. .

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Tammy Parisian Date: 8/29/19
Signed: Tammy Parisian

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: See attached Date: _____
Signed: _____
E-Mail: _____



SERVICE REPORT

WORK ORDER:

93613

CUSTOMER PO:
19293/4099

DATE: 07/19/2019

CUSTOMER: US ARMY RESERVE - PL (AR#:10343)
STREET: 5363 PERU STREET, ROUTE 9
CITY: PLATTSBURGH, NY 12901
CONTACT: RON VOGL - CELL

DESCRIPTION: SCHED 7/19 8AM WITH LIFT- DO NOT MOVE-JS 7/16// *** LIFT NEEDED - SEE NOTES AND TECHNICIAN NEEDS TO PICK UP NIPPLES, UNIONS, ETC. ***** Quoted - Repair Leak in Small Fan Coil in Gym - Doug (Approved by Customer on 6/11/19-LF)///

CALL TYPE: PLATTSB - AIR CONDITIONING

TROUBLE REPORTED: PL - AIR CONDITIONING

WORK PERFORMED: WO# 4099 CSS19293/NY054

We were asked to check a leak. Our technician made the following notes:

Need lift to make repairs - found small fan coil in gym room leaking from union. Recommend replacing two 1.25 unions and two 1.25x 3-6 nipples.

The pricing shown below covers labor and materials required to do this work. The diagnostic call is being invoiced separately. Please call me at extension #236 if you have any questions. Thank you. (FRASHER, LINDA L. on Jun 11, 2019)

Drained line and unsolder joints on top and bottom of heater. Removed rusted out dielectric fittings. Installed new air vent and boiler drain cap. Solder in new unions and checked for leaks. . (HOWARD; DOUGLAS E. on Jul 19, 2019)

PARTS

LABOR

DATE	LABOR	TECHNICIAN/DESC
07/19/2019	6 (SD)	HOWARD; DOUGLAS E. (Service Repair)

IS JOB COMPLETE? Yes

Customer


Name:

Date: 07/19/2019 12:00 PM


Comments:

Email

Customer Signature

A handwritten signature in black ink, appearing to read "R. B. Kettner".

Employee Signature

A handwritten signature in black ink, appearing to read "R. M.".**Employee**

Name: DOUG HOWARD

Date: 07/19/2019 12:00 PM

Comments: