

Date: 7-11-24

Region: 4C

CSS No.: 91856

FAC ID: WV002

Maximo WO No.: 15415

Asset #:

Priority: 2



Original Work Request:

The OMS shop has a BFP that needs replaced but can't because it needs a new ball valve in order to shut off the water in order to change the BFP. This ticket is to replace the ball valve

Description of Repairs Needed:

In the OMS shop remove, install a 2" backflow preventer with a 2" gate valve on the inlet and exit of the backflow, the existing 4" gate does not completely shut off. Leave the existing 4" gate in place, install a new 2" ball valve past the 4" gate valve, recertify the new backflow valve.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	14	\$ 150.00	\$ 2,100.00
Certify Backflow	1	\$ 700.00	\$ 700.00

Material List:

	Quantity	Cost	Total
2" Backflow Valve (007MIDCDA-OSY-GPM-FZ)	1	\$ 5,268.19	\$ 5,916.06
2" FNPT Full Port Ball Union Valve (2-850TUXL)	1	\$ 485.25	\$ 485.25
Freight	1	\$ 250.00	\$ 250.00
Miscellaneous (pro press, shop supplies, disposal, etc.)	1	\$ 200.00	\$ 200.00
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$2,800.00	\$6,851.31	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$9,651.31	\$1,158.16	\$579.08	\$11,388.55