

Date:

Region: 4C
FAC ID: WV002

CSS No.: 95574
Maximo WO No.: 14280

Asset #:

Priority: 1



Original Work Request:

Leak in the fittings of the air/water separator in the boiler HW loop. Leak has covered the mechanical room floor overnight and needs repaired immediately to start up the main segmented boiler. Recommended contractor: Casto

Description of Repairs Needed:

Labor and materials used to repair the air/water separator fittings in the boiler HW loop. Work completed at the time of investigation to minimize potential possibility of flood of mechanical room.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	10	\$ 122.00	\$ 1,220.00
			\$ -

Material List:

	Quantity	Cost	Total
fittings/piping	1	\$ 73.60	\$ 73.60
trip charge for fittings	1	\$ 52.50	\$ 52.50
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,220.00	\$126.10	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,346.10	\$161.53	\$80.77	\$1,588.40