

Date: 3-12-24

Region: 4C
FAC ID: WV002

CSS No.: 97018
Maximo WO No.: 15225

Asset #:

Priority: 2



Original Work Request:

AHU #2 has a refrigerant leak

Description of Repairs Needed:

Work is to replace the thermal expansion valve on York AHU #2. Please note, quote is only to replace TXV, if additional refrigerant is required once repair is completed, then additional charge for the amount of refrigerant used will be added as separate charge.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (Mech)	12	\$ 132.00	\$ 1,584.00
Tech (Mech Helper)	8	\$ 112.00	\$ 896.00

Material List:

	Quantity	Cost	Total
TXV (VAL 19777-NUECO)	1	\$ 310.31	\$ 310.31
S&H	1	\$ 32.50	\$ 32.50
Miscellaneous (refrigerant recovery, etc.)	1	\$ 90.00	\$ 90.00
Trip Charge	40	\$ 1.75	\$ 70.00
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$2,480.00	\$502.81	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,982.81	\$357.94	\$178.97	\$3,519.72