

Date:

Region:

FEMS/CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



Original Work Request:

Fire panel in alarm for CO at Motor Pool, Rm 103

Description of Repairs Needed:

Proposal is for initial investigation and return to install new CO Detector and battery for fire panel

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1) - Investigate	4.5	\$ 150.00	\$ 675.00
Tech (1) - Repair	4.5	\$ 150.00	\$ 675.00
			\$ -

Material List:

	Quantity	Cost	Total
CO Detector - FCO-951	1	\$ 235.00	\$ 235.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,350.00	\$235.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,585.00	\$190.20	\$95.10	\$1,870.30