

Date: 6-10-24

Region: 4C

FAC ID: WV005

CSS No.: 98082

Maximo WO No.: 15843

Asset #:

Priority: 1



Original Work Request:

No A/C Daikin Systgem is throwing an Error H7 code for the supply zone. FTS state that it went out on Monday/Tuesday 20-21 May 2024.

Description of Repairs Needed:

Investment is to replace investigate issues with condenser on Daikin systems causing H7 error code.

Labor:	Labor Hrs	Labor Rate	Total
Tech (1)	3.5	\$ 132.00	\$ 462.00
Trip Charge	1	\$ 131.25	\$ 131.25

Material List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

--

Estimate Summary:

Labor	Material	Equipment
\$593.25	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$593.25	\$71.19	\$35.60	\$700.04