

Date:

Region:

CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



**Original Work Request:**

No A/C Daikin Systgem is throwing an Error H7 code for the supply zone. FTS state that it went out on Monday/Tuesday 20-21 May 2024.

**Description of Repairs Needed:**

Investment is to replace the condenser fan motor and fan blade on Daikin VRF Codnenser #1 (M# REYQ96; S# A000151) that serves the offices

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	8	\$ 132.00	\$ 1,056.00
Trip Charge	60	\$ 1.75	\$ 105.00

**Material List:**

	Quantity	Cost	Total
2534435 Motor - Mason & Barry	1	\$ 466.20	\$ 466.20
2097860 Fan Blade - Mason & Barry	1	\$ 196.20	\$ 196.20
Shipping & Handling	1	\$ 84.50	\$ 84.50
Miscellaneous Parts (coupling, nipples, shop supplies)	1	\$ 45.00	\$ 45.00
		\$	-
		\$	-
		\$	-

**Equipment List:**

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$1,161.00	\$791.90	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,952.90	\$234.35	\$117.17	\$2,304.42